

The Reconditioning Process:

After careful removal of the refrigerator from the RV, camper, trailer, or boat the following process begins:

1. The cooling unit is removed from the cabinet of the refrigerator.
2. Next, the cooling unit is tested with our specialized equipment. This equipment allows us to test the unit for leaks under a great deal of pressure.
3. If a simple leak is detected we repair it with our certified processing technique.
4. If the core is badly rusted or deemed not repairable, we will replace the defective part/parts or in some cases replace the entire cooling unit core.
5. RV refrigerators operate on 300lbs. of pressure but, with this process the cores are tested under 1000lbs. for three hours. This ensure is to that the process was successful.
6. Unit is recharged to original factory specs.
7. If this process checks out, then the cooling unit is re-installed back into the refrigerator cabinet.
8. We prefer to individually seal all our refrigerator evaporators in urethane form.
9. All of our units are reconditioned and repaired. New and used come with a three-year warranty on all parts and labor.